


FIG. 2

(a)

REVOLVING AXIS z



(b)

REVOLVING AXIS z





FIG. 3






FIG. 4





FIG. 5










FIG. 6





















FIG. 9



10/18 FIG. 10





FIG. 11



(b)




FIG. 12






FIG. 13

F=0.8 F=0.9 F=1.0 F=1.1 (b) F=0.8 F=0.9 F=1.0 F=1.1

FIG. 14



(b)



(c)




FIG. 15




FIG. 16




FIG. 17






FIG. 18




MEASURE TWICE WITH THE SAME PHASE

REVOLVING AXIS Z MEASURE THREE TIMES WITH THE SAME PHASE

FIG. 19



IMAGING START TIME (β =0)



IMAGING END TIME (β =2 π)

